# Lenovo

# Moto g power 2025



Moto g power 2025 Level 3 – Service Manual

## DISCLAIMER & WARNING

INFORMATION CONTAINED IN THIS DOCUMENT IS PROPRIETARY AND CONFIDENTIAL AND SHOULD NOT BE COPIED, DISTRIBUTED OR REPRODUCED IN WHOLE OR IN PART, OR DISCLOSED IN ANY MANNER TO ANY THIRD PARTY WITHOUT THE PRIOR WRITTEN CONSENT OF MOTOROLA. ALL CONFIDENTIAL INFORMATION REMAINS THE PROPERTY OF MOTOROLA. EXCEPT FOR THE RIGHT TO ACCESS AND USE THIS CONFIDENTIAL INFORMATION IN FURTHERANCE OF THE REPAIR OF YOUR PERSONAL DEVICE, NO LICENSE OR OTHER RIGHT TO USE THIS CONFIDENTIAL INFORMATION OR TO MOTOROLA'S INTELLECTUAL PROPERTY IS GRANTED OR IMPLIED.

MOTOROLA IS NOT LIABLE FOR ANY DAMAGE OR DEFECT DETERMINED TO BE CAUSED BY A NON-AUTHORIZED SERVICE PROVIDER, SELF-REPAIR OR OTHER NON-PROFESSIONAL REPAIR OF THE DEVICE. SUCH DAMAGE OR DEFECT IS NOT COVERED BY THE WARRANTY. MOTOROLA IS NOT LIABLE FOR ANY RESULTING INJURY (INCLUDING DEATH) OR DEVICE SAFETY ISSUE CAUSED BY SUCH REPAIRS.

THIS DOCUMENT INCLUDES TECHNICAL INSTRUCTIONS FOR REPLACING GENUINE MOTOROLA PARTS AND IS INTENDED FOR INDIVIDUAL TECHNICIANS WITH KNOWLEDGE, EXPERIENCE, AND THE TOOLS REQUIRED TO REPAIR ELECTRONIC DEVICES.

READ THE ENTIRE DOCUMENT FIRST. IF YOU ARE NOT COMFORTABLE PERFORMING THE REPAIRS AS INSTRUCTED IN THIS DOCUMENT, DO NOT PROCEED.

FAILURE TO FOLLOW THE REPAIR INSTRUCTIONS OR TO USE AUTHENTIC/GENUINE PARTS OR PROPER TOOLS MAY CAUSE FIRE OR OTHER SAFETY ISSUES AND COULD LEAD TO PERSONAL INJURY (INCLUDING DEATH).

FAILURE TO FOLLOW THE REPAIR INSTRUCTIONS OR TO USE AUTHENTIC/GENUINE PARTS OR PROPER TOOLS MAY DAMAGE THE DEVICE OR COMPROMISE THE DEVICE'S FUNCTIONALITY, WATER RESISTANCE OR PERFORMANCE.

NOTO 3 power 5056

LENOVO COPYRIGHT PROTECTED

BY ACCESSING THIS DOCUMENT, RECIPIENT ACKNOWLEDGES, ACCEPTS AND AGREES TO THE FOREGOING.

© 2025, Motorola Mobility LLC

# **REVISION HISTORY**

Revision	Date	Notes
1	02/14/2025	Initial Release.



# TABLE OF CONTENTS

DISCLAIMER & WARNING	2
Revision History	3
Table of Contents	4
L3 Parts List and Image	6
Front View	7
Back View	8
Trouble Shooting Guide	
Power failure check	9
Audio glitchesUSB Fault	10
USB Fault	15
LCD Fault	16
Camera FaultFlash Fault	18
Flash Fault	20
USIM/T-Flash Fault	
The motor test is invalid	22
A+G-Sensor Test Fail	
M-Sensor Test Fail	23
PL-sensor Fault	24
Unable To Charge Faulty	24
Unable To Boot Fault	26
Auto-on	26
Service Code	27
Board Layout	28
Front Diagram	28
Dack Diayraiii	∠૭
Block Diagram	30
Schematic	31
Schematic BB_POWER_PDN1	31
BB_POWER_PDN2	32
BB_POWER_IO	33
BB_1	34
BB_2	36
BB_3	36
BB_4	37
BB_AUXADC_Thermal	38
POWER_MT6377_Buck	39
POWER MT6377 LDO	40

#### Moto g power 2025 Level 3 – Service Manual

POWER_MT6377_General					40
POWER_MT6377_Clock					41
POWER_MT6319_Buck					42
Main Charger_PD_Controller					42
Memory_UFS_LPDDR4X					43
Charge Pump					44
Bat_OVP					45
Wireless Charger					
SPK PA/REC PA/MIC/HAC					
MIC					48
3.5mm_Earphone  CAMERA_Rear_Front  Test_Points  LED Flash  Sensor	OTEGTED	LENOVO			49
CAMERA_Rear_Front			Op <sub>ha</sub>		50
Test_Points					54
LED Flash	kinto g P	0We <i>r 20</i> 22			56
Sensor	Mio	-0<3		£ 1	57
LCD Display SUB CONN				1 77 1	59
SIM_SD	/				61
FBRX			\		62
ENDC PA			1 8	賣	62
PRX/DRX_LNABANK N77-PA-1T2R	02/14	/2025	9	1 & 1	63
N77-PA-1T2R	04/17	12020	0W6		64
N77-LFEM-2R			1	IŏI	64
WCN MT6631		/	50	120	65
SAR		/		131	66
SAR				/3/	67
18		Moto 9 po	di j	77	
13	00 40///	Ou N	Ch		
(B)	COLLECTEC	NOVO COPYRIC	2		
	add THE	JIRVana			

# L3 Parts List and Image

Table 1. L3 Parts List

Location	Part Number	Ref.	Commodity	Qty	Part Level	Description	Function	Remark
1	SC98E37671	U1801	IC	1	L3	IC, PMIC, WFBGA, 207PINS, MT6377W/A	Power Management	
2	SC98E37672	U2201	IC	1	L3	IC, PMIC, WLCSP, 45PINS, MT6319NP/A	Integrated Circuits	
	S938C66937	J3502, J3503	Connector	2	L3 <sup>LE</sup>	LC4312AA000107+CONN_ 24Pin		
	S938C84152	J3801	Connector	1	L2.5	LC4312AA000158+CONN, BB, Socket, 10 pin, P0.		
	S938D67757	J4004	Connector	g po	ver 20 L2.5	LC4320AA000125+ HOLDER, Nano+TF		
	S948D21192	J3501, J3900	Connector	2	L3	LC4312AA000120+CONN, BB, Socket, 40pin		
	S948D67715	J4001	Connector	1	L2.5	LC4320AA000070+CONN, Nano, SIM, PIN, PUSH	i e	
3	S948D88394	J2901	Connector	14/	L2.5	LC4312AA000442+CONN, BB, Socket, 10pin, 15A	OVO	Battery Connector
	S948E42607	J3901	Connector	1	L3	LC4312AA000536+CONN, BB, Socket, 50pin, 5A	COBY	
	S948E53970	J4003	Connector	1	L2.5	LC4320AA000181+CONN, Nano+SD, PIN PUSH	/	
	S948E13232	J1004	Connector	1	L2.5	LC4310AA000179+CONN, TypeCUSB, 24 pin, 7A		On USB Board
	S938E14994	MIC3301	Microphone	1	L2.5	LC2430AA000148+MIC, BOT2.75X1.85XH0.95mm		
		1	PROTECTE	LHN	нүчо	OOVONAL	'	

#### **NOTE**

L3 parts are not commonly stocked, contact our USA distributors partners to request prices and lead times.

## **Front View**




Figure 1. Front View

## **Back View**




Figure 2. Back View

## TROUBLE SHOOTING GUIDE

After the SMT of the production line is completed, X-RAY inspection will be carried out before cutting the board, according to the actual situation, X-RAY inspection cannot ensure 100% good products, so some faulty boards may be missed after X-RAY inspection. If a faulty board is found during the test, the first step is to re-conduct the X-RAY inspection, and carefully check whether there are problems such as continuous welding, lap welding, and virtual welding.

#### Power failure check

The main fault phenomena caused by power failure are: failure to turn on, large leakage current when shutdown, and large current when starting up. The main causes of this problem are: false soldering, power supply filtering or short circuit to ground of ESD devices, burning of devices connected to power supplies, etc.

LENOVO

The steps to locate and resolve such issues are as follows:

- Check the soldering of the components connected to the power supply, whether they are virtual soldering, or connected to the surrounding devices.
- Use a multimeter to eliminate whether there is a short circuit of the power supply to the ground, and check the cause of the short circuit step by step (mainly: tin, IC burnout, ESD protection device breakdown, capacitor breakdown, etc.).
- 3. Boot up to test whether the output of each power supply is normal.

If the output value of a power supply is abnormal, check whether there is a problem with the welding of the relevant filter capacitor and whether it is broken down, and replace it if the filter capacitor is broken; After eliminating them one by one, the damage to the main chip can finally be located.

The following table shows the test locations of each power supply and its normal boot value.

MT6377 Default on Default Voltage step lmax **BUCK** name Vout (V) Application voltage (V) (mV)(mA) (Y/N) BUCK1/2 0.75 0.4~1.193 6.25 10,000 CPUB **BUCK3** 0.725 0.4~1.193 6.25 5,000 Y Digital core **BUCK4** 0.75 0.4~1.193 6.25 5,000 Y CPUL **BUCK5** 0.7 0.4~1.193 6.25 γ RF digital 1,200 ٧ **BUCK6** 1,125 0.4~1.193 6.25 2,500 DRAM VS1 1.8~2.2 12.5 2,200 Y SYS LDOs power 2.0 SYS LDOs power VS2 1.45 1.2~1.5 12.5 2,500 ٧ **VPA** 0.6 0.6~3.4 50 1,500 N LTE/NR PA

Table 3-2. Buck converter brief specifications

Table 3-3. LDO types and brief specifications

LDO name	Туре	Controller power domain	Input power domain	Vo (V)	I_rated (mA)	Application
VA12	SLDO_600	VSYS_SMPS	VS2_LDO2	1.2	600	ABB
VAUD18	SLDO_300	VSYS_LDO1	VS1_LDO1	1.8	300	Audio
VAUD28	ALDO_200	VSYS_LDO1	VSYS_LDO1	2.8	200	Audio
VAUX18	ALDO_50	VSYS_LDO2	VSYS_LDO2	1.84	50	AUXADC
VBIF28	ALDO_50	VSYS_LDO2	VSYS_LDO2	2.8	50	Battery interface
VCN33_1	DLDO_800	VSYS_LDO1	VSYS_LDO1	3.3/3.4/3.5/3.6	800	Connectivity
VCN33_2	DLDO_800	VSYS_LDO1	VSYS_LDO1	3.3/3.4/3.5/3.6	800	Connectivity
VCN18	SLDO_1200	VSYS_LDO1	VS1_LDO2	1.8	1,200	Connectivity
VRFCK	VDCXO	VSYS_LDO2	VSYS_LDO2	1.6	5	DCXO
VBBCK	VDCXO	VSYS_LDO2	VIO18	1.2	5	DCXO
VXO22	VDCXO	VSYS_LDO2	VSYS_LDO2	2,24	25	DCXO
DVDD18_DIG	VDIG18	VSYSSNS	VSYSSNS	1,8	2	PMIC internal digital power
VM18	SLDO_300	VSYS_LDO1	VS1_LDO1	1.84	300	DRAM
VMDDR	SLDO_600	VSYS_SMPS	VDD2	0.75	600	DRAM
VMDDQ	SLDO_1200	VSYS_SMPS	VDD2	0.6	1,200	DRAM
VEFUSE	SLDO_300	VSYS_LDO1	VS1_LDO2	1.8	300	eFuse
VEMC	DLDO_800	VSYS_LDO2	VSYS_LDO2	2.55/2.9/3	800	eMMC and UF
VUFS	SLDO_1200	VSYS_LD01	VS1_LDO1	1.86	1,200	UFS
VIO18	SLDO_600	VSYS_LDO1	VS1_LDO2	1.8	600	I/O and eMMO
VSRAM_MD	SLDO_600	VSYS_SMPS	V52_LDO1	0.85/0.55	600	SRAM
VRF18	SLDO_1200	VSYS_LDO1	V51_LDO2	1.84	1,200	RF
VRF09	SLDO_800	VSYS_SMPS	VS2_LDO2	0.9	800	RF
VRF12	SLDO_800	VSYS_SMPS	VS2_LDO2	1.2	800	RF
VRFVA12	SLDO_600	VSYS_SMPS	VS2_LDO2	1.2	600	RF ABB
VRFIO18	SLDO_300	VSYS_LDO1	VS1_LDO1	1.82	300	RF IO
VRTC28	VRTC	VSYSSNS	VSYSSNS	2.8	2	RTC
VMCH	DLDO_800	VSYS_LDO3	VSYS_LDO3	3/2.9/1.86	800	SD card
VMC	DLDO_200	VSVS_LDO3	VSYS_LDO3	3/2.9/1.86	200	SD card
VSIM1	DLDO_200	VSVS_LDO2	VSYS_LDO2	1.86/2.9/3	200	SIM1
VSIM2	DLDO_200	VSYS_LDO2	VSYS_LDO2	1.86/2.9/3	200	SIM2
VSRAM_PROC1	SLDO_600	VSYS_SMPS	VS2_LDO1	0.85/0.55	600	SRAM
VSRAM_PROC2	SLDO_600	VSYS_SMPS	VS2_LDO1	0.85/0.55	600	SRAM
VSRAM_OTHERS	SLDO_600	VSYS_SMPS	VS2_LDO1	0.75/0.55	600	SRAM
VUSB	ALDO_200	VSYS_LDO2	VSYS_LDO2	3.07	200	USB
VIBR	DLDO_200	VSYS_LDO1	VSYS_LDO1	1.8/1.2/2.8/3/3.3	200	Vibrator
VIO28	DLDO_200	VSYS_LDO1	VSYS_LDO1	1.8/1.2/2.8/3/3.3	200	I/O and sensor
VFP	DLDO_200	VSYS_LDO3	VSYS_LDO3	1.8/1.2/2.8/3/3.3	200	Fingerprint
VTP	DLDO_200	VSYS_LDO3	VSYS_LDO3	1.8/1.2/2.8/3/3.3	200	Touch panel


-~dd THDIRYan~

## **Audio glitches**

The audio part mainly includes four parts: speaker, receiver, mic and headphones. First, according to the defective phenomenon, distinguish which part is the problem, and then analyze it according to the following modules.

#### (1) Speaker loop

The speaker of the M383 mobile phone is on a small board and is connected to the motherboard via FPC. External power amplifier is used, and the channel device is on the motherboard. The schematic diagram of the speaker audio output is as follows:



Common Speaker faults and causes are as follows:

- 1. Reasons why SPK has no ringtone:
  - Whether the SPK itself is broken, or the SPK is missing:
  - Whether there is any abnormality in the SPK path device on the small board;
  - Whether the FPC connected to the motherboard and the small board is loose or falling off;
  - Whether the audio PA (U2001) is defective;
  - The above picture is whether there is a problem with the device on the SPK\_OUT\_P/N;
  - Software Issues.


02/14/2025

- 2. SPK ringtone is small or noisy:
  - The volume of the software is set incorrectly;
  - Whether the SPK\_OUT\_P/N capacitance to ground and the ESD device are reversed or broken down and short-circuited;
  - SPK ontological causes.
- 3. There is no ringtone when the machine is switched on and off, but the engineering test SPK is OK:
  - The ringtone is turned off when the scene mode is set;
  - Software problems, no boot ringtone.
- (2) Receiver loop

The earpiece of the M383 mobile phone is embedded in the front case of the mobile phone and connected to the motherboard by a shrapnel. Mainly used for phone calls. The following figure shows the receiver loop.

LENOVO

COP




Common Receiver Faults and Causes are as follows:

- 1. Receiver no sound:
  - Receiver is poorly assembled, and the shrapnel and board are in poor contact;
  - Virtual soldering of devices on AU\_HSP/N lines;
  - Receive ontology is bad;
  - Volume setting or software problems.
- Receiver noise or low volume: 2.
  - Receiver incoming material is poor;
  - Device soldering problems or burnout on the AU\_HSP/N line;
  - Software issues.

#### (3) MIC circuit


The M383 contains 2 MIC circuits. One is on the small board as the main MIC, and the other is on the motherboard as the secondary MIC, where the motherboard MIC is not assembled by default. The 2 MICs are SMD silicon MICs.

The schematic diagram of the secondary MIC loop on the motherboard is as follows:



LENOVO COPYRI

The schematic diagram of the main MIC of the small board is as follows:




Common faults and causes of MIC are:

- 1. MIC cannot send or record:
  - MIC welding is poor;
  - False soldering of devices on the motherboard MIC\_P/N line;
  - Ground filter capacitors and ESD devices are short-circuited to ground;
  - The MIC body is bad; (If there is no sound after testing the MIC recording, it is also possible that the speaker channel is bad).


LENOVO

- 2. MIC has noise or low sound:
  - MIC body is bad;
  - The MIC dust filter is not pasted, and the sound inlet hole is dusted;
  - The MIC sealant sleeve is not installed;
  - Software problems;
  - The conductive cloth on the small board is not pasted as required;
- (4) Headphone circuit

The headphones used in the M383 phone are standard 3.5mm headphones. The circuit schematic diagram is as follows:



ENOVO COPYRI



Common faults and causes of headphones are:


- The headphones have no sound:
  - The headphones are not plugged in;
  - Earphone connector pad virtual soldering;
  - Whether the device on the AU\_HP\_L/R line is soldered or damaged;
  - Whether there is damage to the TVS and capacitance to the ground;
  - The relevant circuits inside the chip are damaged or soldered.
- The earphone cannot be identified when inserted and unplugged: 2.
  - The earphone detects whether the circuit device on the HP\_EINT is soldered or damaged;
  - Whether the shrapnel of the earphone socket is in good contact with the motherboard;
  - ESD device short circuit to ground;
  - Software reasons.
- LENOVO COPYRIGHT P. The MIC of the earphone does not send a call:
  - The earphone is not plugged in place.

LENOVO COPYRIGH

#### **USB** Fault


During the test, the fault of "failure to open the serial port" often occurs. The main reasons for this failure are:


- 1. The mobile phone cannot be turned on, please refer to the maintenance due to the failure to turn on;
- 2. The USB test point is oxidized, and there is no good contact with the fixture;
- 3. USB connector virtual welding;
- 4. Due to the USB circuit itself, please check whether the device is soldered and whether it is connected to the test point. Whether the TVS device and the surge device to the ground are reversed or broken down, resulting in a short circuit to the ground of USB\_DM, USB\_DP, and VBUS.



#### **LCD Fault**

The M383 uses a 6.78-inch LCD that is connected to the motherboard via a board connector. The schematic diagram of this part of the circuit is as follows:





Common faults and causes of LCD modules are:

- 1. LCD black screen:
  - The LCD is not installed well or the contact with the fixture is poor;
  - If the LCD backlight circuit is broken, check whether the backlight enable pin is pulled up, check whether the backlight chip circuit has soldering problems, and check whether the backlight IC input and output pin PWM control pin is normal;
  - The LCD itself is faulty;
  - The conductive cloth on the LCD has burrs that touch the LCD backbare feet;
  - Whether the Schottky diode is broken down;
  - The bias voltage output (VSP/VSN) is abnormal.
- LCD white screen or blurred screen: It means that the LCD backlight circuit is OK, but the display part is abnormal. The causes of failure are usually as follows: YRIGHT PROJECTION
  - Poor contact of LCD connectors, poor soldering or poor contact with fixtures;
  - Whether the EMI device is soldered or short-circuited with tin;
  - Software issues.
- 3. LCD black spots, bright spots, black lines, streaks Fault cause: LCD body is bad.




LENOVO


#### **Camera Fault**

M383 is designed for three cameras, one front camera is connected to the motherboard through connector J3503, one rear main camera is connected to the motherboard through connector J3501, and one rear auxiliary camera is connected to the motherboard through connector J3502. The control of the Camera is done via the I2C bus.

#### Rear Camera 50M(OIS)



#### Front Camera 16M/32M




Common camera faults and causes are as follows:

- Camera initialization failed, and the main interface of Camera cannot be entered: LENOVO COPYRIGHT PROJECTION
  - Camera contact is poor;
  - Camera body failure;
  - The power supply of Camera Power is abnormal
  - EMI device problems, virtual soldering or tin damage;
  - The software is abnormal.
- The Camera preview screen or color is abnormal:
  - The Camera is not in good contact;
  - EMI device soldering problems; \$202 Jamod 6 olow
  - Reboot after factory reset.
- Camera can't store photos:
  - The memory of the body is insufficient, and there is no T card inserted;
  - The software is abnormal.
- For other problems with the Camera, please replace the Camera and try to confirm whether the Camera itself is faulty.

J power 2025

#### Flash Fault

M383 rear flash:





The reasons for flash test FAIL are as follows: Moto g power 2025

- Chip virtual soldering;
- The flash body is damaged or soldered.

#### **USIM/T-Flash Fault**

M383 with Nano+Nano/SD card holder; The signal that comes out is connected to the CPU.





- The reasons for not knowing the card are usually as follows:
  - Poor contact of the card seat;
  - The ESD protection device is broken down and short-circuited to the ground;
  - Whether there is virtual welding in the card seat;
  - Whether the card is inserted beyond the stroke or reversed.
- T-Flash read and write test failure:
  - T-flash is a faulty card;


Noto 9

- LENOVO COPYRIGHT PROJECT There may be a short circuit in the resistor, or a virtual soldering phenomenon;
- Software reasons.
- T-Flash cannot be transmitted via USB:
  - T-Flash itself fails to read and write test;
  - Software malfunction;
  - If the USB is faulty, check whether the USB path is normal.

LENOVO COPYRIGHT PROTECTED

#### The motor test is invalid

The M383 uses a linear motor, located on a small board, which is connected to the motherboard through FPC, and the motor drives the positive and negative outputs of the IC.




Common motor failures and causes are:

- 1. No vibration of the motor:
  - The shrapnel of the small plate is in poor contact with the motor
  - The motor itself is bad.
- The motor has a weak sense of vibration;
  - The motor body is bad;
  - Software setting reasons.
- 3. The motor vibrates from time to time: the motor body is a problem.
- 4. Motor vibration noise:
  - Structural assembly problems;
  - Motor ontology reasons.

#### **A+G-Sensor Test Fail**

M383 A+G-Sensor SPI Data reading communication.




Common faults and their causes are:

- Function NG: Check whether the module circuit has soldering or short circuit faults.
- Check whether the IC power supply is normal. Dower 2025

#### **M-Sensor Test Fail**

M383 M-Sensor I2C data reads communication.




LENOVO COPYRIGHT PROTECTED

Common faults and their causes are:

- Function NG: Check whether the module circuit has soldering or short circuit faults.
- Check whether the IC power supply is normal.


#### **PL-sensor Fault**


M383 PL-Sensor, I2C Data reading communication.




## **Unable To Charge Faulty**

#### **Sub Connector**







# Battery Connector



#### Switching Charger Power Path





Abnormal problems include problems such as not being able to charge, and the possible causes are as follows:

- 1. The surge protection device on the motherboard is abnormal and short-circuited to the ground;
- 2. The USB interface of the small board is loose and the contact is poor;
- 3. The OVP chip or Switching Charger is damaged or soldered;
- 4. The battery connector is in poor contact or deformed, and the software cannot identify the battery;
- 5. Poor contact of FPC of main and auxiliary boards.

#### **Unable To Boot Fault**

The failure to turn on fault is the fault with the highest probability of the mobile phone. Software problems, soldering problems, and device failures are the main factors that cause the machine to fail to boot. During the maintenance process, it can be roughly positioned with the LCD, the boot current, and the keyboard.

- 1. Large shutdown leakage current: The main fault reason is that the devices connected to VBAT have a short circuit to ground. It is usually caused by the burning or soldering of the TVS tube.
- 2. No current when booting up, no LCD display:
  - The boot button is not plugged in; \$200, 1940,000
  - Poor contact of the battery connector (can be troubled by plugging and charging).
- 3. Static display of LCD when booted: usually due to software reasons, you need to re-download the software.
- 4. The LCD display is black when turned on; At present, it is found that it is mainly caused by memory air welding and virtual welding; or software problems, you need to re-download the software;
- 5. There is virtual welding in the FPC welding of the side key, and there is a fall off the boot button of the side key.

#### Auto-on

- 1. When the power supply is connected, the USB is plugged in, and the power is not turned on and the reboot does not stop: it is because the software needs to be connected to the power supply to turn on;
- 2. The FPC buckle of the motherboard and small board will also lead to automatic boot;
- The FPC body of the side button is bad, and the PWRKEY will automatically start up due to a short circuit.

ENOV

# **SERVICE CODE**


Commonly used Service codes, for your reference.

Service Code	Function
*#06#	View your phone's IMEI number.
*#*#4636#*#*	Display battery information, WLAN status, and usage statis.
*#*#225#*#*	Display Calendar data stored on your phone.
#*#426#*#	Run Google Play Services diagnostics.
*#67#	Display call forwarding information on your phone.
*#61#	See how long it takes to forward calls.
*31#	Turn on caller ID.
#31#	Turn off caller ID.
*43#	Turn on call waiting.
#43#	Turn off call waiting.




# **BOARD LAYOUT**

# **Front Diagram**




## **Back Diagram**



# **BLOCK DIAGRAM**


# BB System Block




# SCHEMATIC

If you need or involve the key component schematics (e.g., PMIC/CPU), please contact SVCPE@lenovo.com directly.


#### BB\_POWER\_PDN1




#### BB\_POWER\_PDN2





## BB\_POWER\_IO



#### **BB\_1**







Schematic design notice of "BB\_1" page.

Note 1: The load cap. have to be placed as close to REFP ball as possible.

Note 2: "AUD\_DAT\_MOSI0" and "AUD\_DAT\_MOSI1" pin features in strapping pin to enable JTAG.

AUD_DAT_MOSI0	AUD_DAT_MOSI1	AP JTAG	IO JTAG	DAP_SONIC/DAP_MD32
L (Default)	L (Default)	N/A	N/A	N/A
L (Default)	H (by external PU)	SPI0_CSB, SPI0_CLK, SPI0_MO, SPI0_MI, KPCOL1	N/A	N/ADOW
H (by external PU)	10 g	SPI0_CSB, SPI0_CLK, SPI0_MO, SPI0_MI, KPCOL1	EINT[8:12]	10 P)
H (by external PU)	H (by external PU)	N/A	N/A	N/A

Note 3: "EINT1" and "PERIPHERAL\_EN10" pin features in strapping pin to booting (eMMC/UFS/Reserved).

EINT1	PERIPHERAL_EN10	Storage Booting
L (Default)	L (Default)	Only UFS boot
L (Default)	H (by external PU)	Only eMMC boot
H (by external PU)	H (by external PU)	Reserved

Note 4: "AUD\_SYNC\_MOSI" and HW strapping pin to enable DDR.

AUD_SYNC_MOSI	DDR
L (Default)	MCP
H (by external PU)	DSC

Note 5: "AUD\_DAT\_MISO1" is MT6377 strapping pin to select VEMC Voltage.

AUD_DAT_MISO1	VEMC	Application
L	2.5xV	UFS 3.1
H (by ext. PU)	3.0V	UFS 2,x

## **BB\_2**





Table 2-26. Mode selection


Pin name	Description	
[0] PERIPHERAL_EN10 [1] EINT1	00: UFS 01: eMMC 10: Forbidden 11: Forbidden	
[0] AUD_DAT_MOSI1 [1] AUD_DAT_MOSI0	00: Default 01: AP_JTAG_VCORE 10: MD_JTAG 11: DAP	
[0] AUD_SYNC_MOSI [1] EINT4 [2] EINT5	000: LP4x MCP 001: LP4x DSC	



Schematic design notice of "BB\_4" page.

Note 1: for LP4 R4001 is 60.4 ohm (1%).

### BB\_AUXADC\_Thermal



Moto g power 2025

Schematic design notice of "BB\_AUXADC\_Thermal" page.

Note 1: SW Default Configuration is as followings:

AUXADC\_VIN2: AP Temp.

AUXADC\_VIN3: MHB PAMiD Temp.

AUXADC\_VIN4: NR PAMID Temp.

Note 2: If your design or placement is different with SW Default Config.

Please refer to "MT6835 Thermal User Manuel.docx" and modify SW setting.

Note 3: AUXADC\_VIN2 ~ 4 must connect to MT6377 owing to TIA2.0 Design Constraint.


If not, you will lose MD/GPS thermal protection and throtting function.

DIOTECTION OF STATE O


LENO

600


### POWER\_MT6377\_Buck



# POWER\_MT6377\_LDO




# POWER\_MT6377\_Clock




### POWER\_MT6319\_Buck

MT6319NP 4-Phase Buck (VMODEM, VSRAM\_MODEM, VGPU)

PMIC GND-ball connect to input cap. GND-pad firstly.



#### PD PHY: AW35615HCSR



Schematic design notice of "Memory\_UFS\_LPDDR4X" page.


Note 1: Please refer to power supply related page select LDO\_VOUT / BUCK\_LX output voltage properly for LPDDR4X.

Note 2: DRAM ZQx resistor = 240ohm (1%) that must be connected to VDDQ.

Note 3: Please refer to uMCP vendor's datasheet or MTK common design notice to get the recommendation bypass cap.Value for VCC/VCQ/VDDI power domains of UFS.


Note 4: VDD2 VDDQ decoupling cap: closed to DRAM ball.

Please also refer to MMD and layout guide for placement.




### Bat\_OVP

### **Battery Connector**



# **Wireless Charger**




AD2	AD1	Address(7-bit)
GND	GND	0x34
GND	DVDD	0x35
DVDD	GND	0x36
DVDD	DVDD	0x37

# PA FOR SPK 1, FS1894SU C2238 0R AW88194A C2238 22nF AW88394 C2238 22nF 2, FS1894SU R2219 and R2220 NC AW88194A R2219 and R2220 NC AW88394 R2219 and R2220 A.7K [15,32,39] SCL6 [15,32,39] SDA6 C3 C4 AD2 AD1 LENC (2C ADDRESS(7-bit):Default 0x36 PA FOR HAC Moto g power 2025 I2C ADDRESS(7-bit):Default 0x37 Motor TRIG/INTN VIB\_INT>> HDP RSTN R3263 0R SCL HDN В1 SDA VJBR\_SDA11 >> [14] C3264 C3263 NC/100KR

I2C ADDRESS(7-bit):Default 0x58


### **MIC**

#### Main Microphone




# 3.5mm\_Earphone

#### **AUDIO SWITCH**



### **CAMERA\_Rear\_Front**

Rear Camera 50M (OIS)




### Front Camera 16M/32M FRONT\_OWI\_DIN FRONT\_OWI\_DIP FRONT\_OWI\_DIN FRONT\_CAM\_DSP Main LDO AVDD 2.8V U3501 OCP1203AV28AD 主摄AVDD-2.8V供电 CAM\_AVDD\_2V8\_EXT AVDD\_LDO\_EN GND1 GND2 [14] ΕN R3517 C3501 Moto 9 power 2025 LENOVO ROTECTED MCAM\_AGND [35] COPYRIGHT PA **8M AVDD 2.8V** U3504 R3525 Wide\_CAM\_AVDD OUT GND1 GND2 EN R3503 COPYRIGHT PROTECTED Main LDO DRV\_VDD 2.8V U3502 OCP1203AV28AD CAMERA\_DRV\_VDD VSYS o. IN OUT GND1 GND2 CAM\_DRV\_LDO\_EN [15] ΕN R3522 100KR

->>> DRV\_GND

[35]


#### 8M DVDD 1.2V




#### **Flicker** SENSOR\_SCL1 80000065 FV3501 C3542 NC LESD11D5.0CT5G/NC J3506 ⟨ ⟨ SENSOR\_SDA1 [15,38] 800000065 FV3502 LESD11D5.0CT5G/NC J3507 R3535 \_\_\_\_\_\_\_22R VIO18\_PMU 80000065 FV3503 C3547 R3585 J3509 R3584 80000065 LENOVO COPYRIGHT PROJECTA Noto 9 power 2025 FV3504 LESD11D5.0CT5G/NC J3508 LDO CAM IOVDD 1.8V LD07 Moto 9 power 2025 NC/0R AUD18\_PMU U3507 HOTECTED OCP1203AV18AD VSYS OCAMERA\_IO\_VDD 3 GND1 GND2 CAM\_IOVDD\_LDO\_EN R3513 3553 100KR

#### **Test Points**


**Debug Point** 




### GPIO\_SKU\_List




### **GND Spring**






#### **Sensor**


### A+Gyro Sensor (OIS)




#### **M SENSOR**



QMC6308P I2C slave address: (W)OX58H, (R)OX59H




### FPS VCC LDO 3.3V




# LCD Display\_SUB CONN

### LCM\_Backlight




#### **LCM Connector**



### SIM\_SD

#### **SD CARD**





Schematic design notice of "SIM\_SD" page.

Note 1: Let Vpp pin no connect when NFC SIM function is not supported.

Note 2: For better ESD performance, please select suitable components for system protection.


### **FBRX**







### N77-PA-1T2R

N77/78 PA\_Moudle



### **WCN\_MT6631**






#### Schematic design notice of "WCN\_MT6631" page.

Note 1: For R3808 size, please select 0402 size or larger one.

Note 2: Please refer to MT6765 Baseband design notice for VCN33 LDO selection guide.

Note 3: If WiFi 5G not support, connect pin 34 (WF\_5G) to GND.

Note 4: Pin 36 (AVDD28\_FM) must be connected to VCN28 even if FM not support.



# **NFC**

